
Larson Systems Inc.



TWCS Parts List

050-0000-0088-00

Torque Wrench Calibration System








050-0000-0088-00 C Parts List TWCS - Torque Wrench Calibration System

| Rev | Ву | Date | Description |
|-----|-----|------------|---|
| | SMH | 03-24-1999 | |
| Α | SMH | | Updated options |
| В | MDL | 11-12-2002 | Cleared options, changed 011-0-9-00 to 025-1-0280-01, added 025-6-7-00. |
| С | MDL | 07-14-2004 | Changed 025-1000-0280-01 to 025-1000-0396-00 and referenced it instead of calling quantity. |

| Item | Qty | Part Number | Rev | Part Name | PCB Location | Part Length |
|------|-----|------------------|-----|---|--------------|-------------|
| 1 | 1 | 025-1000-0396-00 | | Power Supply, 100-240 VAC 50-60 Hz (USA Plug) | | in. |
| 2 | 1 | 025-0000-0409-00 | Н | TWCS Assembly | | in. |
| 3 | 1 | 060-1000-0045-00 | Е | User Manual - TWCS Series | | in. |
| 4 | 1 | 059-0000-0038-00 | Α | Shipping Crate - TWCS Series | | in. |
| 5 | 1 | 060-2000-0005-01 | Α | Parts List - TWCS | | in. |
| 6 | 1 | 025-6000-0007-00 | Α | Sticker Assembly - TWCS | | in. |

Refer to actual order form to determine power supply.

| Approved by: | Date: Jul | y 19, 2004 |
|--------------|-----------|------------|
|--------------|-----------|------------|





025-0000-0409-00 HTWCS Assembly

Parts List

| Rev | Ву | Date | Description |
|-----|-----|------------|--|
| E | SMH | 02-10-2000 | REM'D ITEMS 4, 5, 7, 8, 10-13, 16, 17, 19, AND 20, ADDED ITEMS 21 AND 22, ITEM 2 WAS 25-0-297-01, ITEMS 9 WAS 25-1-304, ADDED NOTE |
| F | SMH | 12-11-2002 | ADDED ITEMS 23-25, CORRECTED NOTE 1 |
| G | KMP | 12-01-2005 | Change Item 6 (dash No's) -06 was -01, -07 was -02, -08 was -03, -09 was -04, -10 was -05 |
| Н | DAL | 03-02-2007 | 025-0000-0482-02 was 025-0000-0313-01, load cell is now listed on quote list |

| Item | Qty | Part Number | Rev | Part Name | PCB Location | Part Length |
|------|-----|------------------|-----|---|--------------|-------------|
| 1 | 2 | 013-0000-0077-00 | | 6-32 X 1/4 Button Head Cap Screw | | in. |
| 2 | 1 | 025-0000-0482-02 | F | Front Panel Assembly, 2 Line Display (2mv Strain Gage) (torque) | | in. |
| 3 | 1 | 018-0000-1884-00 | F | TWCS Housing | | in. |
| 6 | Ref | 025-0000-0410-06 | J | Torque Cartridge - 100 in-lb (1/4" Drive Sug) | | in. |
| 6 | | 025-0000-0410-07 | J | Torque Cartridge - 200 in-lb (1/4" Drive Sug) | | in. |
| 6 | | 025-0000-0410-08 | J | Torque Cartridge - 500 in-lb (3/8" Drive Sug) | | in. |
| 6 | | 025-0000-0410-09 | J | Torque Cartridge - 108 ft-lb (3/8" Drive Sug) | | in. |
| 6 | | 025-0000-0410-10 | J | Torque Cartridge - 260 ft-lb (1/2" Drive Sug) | | in. |
| 9 | 1 | 025-1000-0329-00 | | TWCS Torque Cartridge Cable (Non Interchangeable) | | in. |
| 14 | 1 | 018-0000-0877-00 | Е | Base Bottom Cover | | in. |
| 15 | 4 | 013-0000-0195-00 | | 6-32 X 1/4 Phillips Pan Machine Screw | | in. |
| 18 | 2 | 013-0000-0020-00 | | 4-40 X 1/4 Button Head Cap Screw | | in. |
| 21 | 4 | 013-0000-0196-00 | | 10-32 X 1/2 SHCS | | in. |
| 22 | 1 | 025-1000-0251-00 | Е | Internal Power Cable (025-1000-0396-XX power supplies, Plugs | | in. |
| 23 | 1 | 018-0000-2014-00 | | 25 PIN COVER PLATE | | in. |
| 24 | 2 | 013-0000-0178-00 | | 4-40 X 1/4 SHCS | | in. |
| 25 | 4 | 013-0000-0114-00 | | 5/16-18 X 3/4 BHSCS | | in. |

a Z Approved by: _________ March 2, 2007

SEE ATTACHED DRAWING



763-780-2131 1-877-780-2131 Fax: 763-780-2182 info@larsonsystems.com

